Appendix 3 - Risk Register

Leys Youth Hub

As at: 26.07.23

		Risk Description	Opp / Threat	Cause	Consequence	Risk Treatment			Gross		Current		t	Target							
Ref	Title						Date Raised	Owner	Р	1	Р	1	Score	Р	1	Comments	Control / Mitigation Description	Date Due	Action Status	% Progress	Action Own
		Costs increase and result in the funding not covering the		Inflation, delay, over	Project becomes unviable or Council funding required to		26.07.23										QS consultancy, accurte spec, regular cost workshops, contingency an inclusion of inflation amoun				H Lewsn
###	Costs increase			specification Construction impacts activities held at the site and		Reduce		I Brooke	3	3	2	3	6	2	3		VE All areas are not used or under utilised, the areas can		In Progress	50%	% and j Wr
	operator loss of ncome		Threat	the operator wants to claim for loss of modelled profit udner the contract	the operator claims for loss of income to the council	Reduce	26.07.23	l Brooke	2	2	2	1	2	2	1		be closed off meaning no impact on other bits of the centre	31.10.23	In Progress	60%	H Lewsr % and j Wr
### 1		Restriction on title stops any future potential disposal of site (no current plans for this)		Restriction on title	disposal or development plans that may arise in the future are prevented	Accept	26.07.23	I Brooke	3	3	2	3	6	2	3		Reduce length of restriction to 10 years		Ongoing	90%	% E Gubb
	Low attendance at	There is lower than projected attendance at the youth work attendances		Lower attendance at youth activities		Reduce	26.07.23	l Brooke	3	3	2	1	2	2	1		Co-designed activity programme, existing youth workers inviolved (positive relationships), comms and engagement plan, consistent youth voice	31.03.24	In Progress	30%	% L Sacke
		Delays to the construction programme with risk to grant funding and increased costs		Delays from contrcator not being ready		Reduce	26.07.23	l Brooke	2	3	2	2	4	2	2		contractor has been involved in the feasibility an cost plan preparation, contractor has booked in availability.	30.09.23	Ongoing	90%	H Lews % and j W

This page is intentionally left blank