## Oxford City Planning Committee Presentation




21/02431/FUL & 21/02432/LBC

Meadow Larkins, Larkins Lane




# ynvog profession oxford oxford city council

#### **Site Location Plan**





# www.oxford.gov.uk





**Existing Block Plan** 






### **Existing Floorplan**















## **Existing South Elevation & Existing East Elevation**




5 South Elevation 1:100








# PLOTONOM OXFORD CITY COUNCIL



7 East Elevation - Ruined Cowshed wall 1:100

























#### **Photos (Ruins of Cowshed)**































**Photos (Orchard looking west towards site)** 

















### **Photos (north along Larkins Lane)**






#### **Proposed Site Plan**





#### **Proposed Floor Plans**



















7 The Stables East Elevation DD 1:100













## **CITY COUNCIL**



**Proposed West (Street) and East** 

(Cowshed) Elevations












East Elevation GG 1:100























Width of new barn volume is 300mm narrower than previously submitted width.


New Barn Short Section







The Cowshed Short Section









## **Existing and Proposed Views from Larkins**Lane











## **Existing and Proposed View over gate of The Barn**



Existing View over gate of 58 Barton Lane











Existing View across paddock from Barton Lane







Existing View from Old High Street








Original stone work to be retained

Brick, concrete block and stonework to be demolished

Indicative location of proposed strip footing

#### **Extent of 1970's reconstruction**





Indicative elevation showing the extent of stonework believed to be modern additions or reconstruction dating back to the 1976 conversion to a dwelling house in yellow. Stonework believed to be original is unhatched. Retention of original stonework in this facade to be finally determined following appointment of main contractor and further on site investigation to establish structural stability. New and replacement stonework will be limestone to match the existing. The remediation and replacement of the poor quality 1970s stonework and pointing in this elevation will improve the quality and character of the building and improve its contribution to the Conservation Area. Additions and alterations as part of works in 1976 are identified within the heritage impact assessment, please refer pages 20-29 of this document for further detail.



## www.oxford.gov.uk

#### Photos of existing conversion



a. 1970s alterations clearly visible around creating of opening for garage door and removal of original gable and break in building line



b. Interior of garage showing modern blockwork and new roof



c. Interior of garage showing modern blockwork alterations to create the gable of the stables and new roof structure




d. Exterior of utility showing example of the modern alterations and poor quality repointing to the stonework evident throughout the building.



## **CITY COUNCIL**


# www.oxford.gov.uk



**Previously Proposed Site Plan** 






















### **Previously Proposed Elevations**

















West Gable Elevation

